

Massey Ferguson MF 7318 2024

Make **Massey Ferguson**

Model **mf 7318**



Construction year **2024**


Serial Number **7318698241**

Inspection date **16 May 2026**

Address of the
inspection **Aparecida de
Goiânia**









General

Value

Note



Serial No

1

Chassis no

2








1




2


Open Hood

	Value	Note	
Engine			3, 4, 5
Pump & Nozzle			6, 7
Electrical			8, 9, 10, 11
Radiator			12, 13
Battery photo			14
Running Engine			
Hydraulic oil leaks	No		





12



13



14

Equipment interior

	Value	Note	
Hours			15, 16
Seat			17, 18
A/C Controle			19, 20
Cabin window			21, 22, 23, 24, 25
Roof			26, 27
Gearbox			28
gearbox-option	Reversor		29
Steering-Wheel			30
Pedals			31
Hydraulic Controls photo			32
command-type	Double Command		33, 34
Monitor			35, 36
Auto Guidance ready	Yes		
Transmission	Semi-automatic		37







15



16



17



30

31

32




Tyres

	Value	Note	
Right Back Tyre			38
Right Back Tyre Condition	Regular		
Tyre image			39
Left Back Tyre Condition	Regular		
Left Front Tyre			40
Left Front Tyre Condition	Regular		
Right Front Tyre			41
Right Front Tyre Condition	Regular		
Tyre Condition	Regular		
Double Wheel		SIM	42
Tyre brand	Pirelli		
Tyre Tread			43
Tyre Tread Left Back			44
Tyre Tread Right Front			45
Tyre Tread Right Back			46




38




39




40




44



42



45




46

Extra options

Value	Note	
Are there any additional?		47, 48, 49, 50
Breakdowns (more than 1 if necessary)	EQUIPAMENTO COM RISCOS NA PINTURA/ MAL-FUNCIONAMENTO PONTOS DE FERUGENS NOS PESOS DIANTEIRO / POSSUE PNEUS FILIPADOS FALTA ANTENA GPS/ MONITOR REGULAR FECHADURA DO CAPÔ AVARIADA/ BETERIA RUIM	51, 52, 53, 54, 55, 56, 57, 58, 59, 60, 61, 62, 63





53




54



55



62




57



60



63



61

Remarks

	Value	Note	
Outside	   		
Engine status	   		
Interior	   		

Disclaimer

Please note that our inspections are performed solely for the purpose of reporting the visible condition of the equipment's major systems and attachments on the day of the inspection and do not include load testing or digging/lifting. These inspections are not designed nor intended to detect latent defects, or conditions that could only be found in connection with the physical dismantling of the equipment or the use of diagnostic tools or techniques. This inspection report includes ratings, comments, and photos of the various components of the item. Knowledgeable buyers are expected to carefully review all of the available information in the inspection report, including all photographs, in order to make the best bidding and buying decision possible.

The information provided in this inspection report is to the best knowledge of the Inspector accurate at the time at which the inspection was performed. Prospective buyers are recommended to undertake their own professional inspection of the equipment prior to completing any purchase of the equipment. All equipment is sold on an as is, where is basis with no commitment made by the seller as to suitability of use or fitness for purpose of the equipment.