

## Massey Ferguson MF 7318 2022

Make **Massey Ferguson**


Model **mf 7318**





Construction year **2022**

Serial Number **7318658657**

Inspection date **22 Jan 2026**

Address of the  
inspection **Aparecida de  
Goiânia**











General


|            | Value | Note |      |
|------------|-------|------|------|
| Serial No  |       |      | 1    |
| Chassis no |       |      | 2, 3 |



1




2








3

Open Hood




|                     | Value | Note |  |
|---------------------|-------|------|-------------------------------------------------------------------------------------|
| Engine              |       |      | 4                                                                                   |
| Pump & Nozzle       |       |      | 5, 6                                                                                |
| Electrical          |       |      | 7, 8, 9,<br>10, 11                                                                  |
| Radiator            |       |      | 12, 13,<br>14                                                                       |
| Battery photo       |       |      | 15                                                                                  |
| Running Engine      |       |      |                                                                                     |
| Hydraulic oil leaks | No    |      | 16, 17                                                                              |





## Equipment interior









|                          | Value          | Note |  |
|--------------------------|----------------|------|-------------------------------------------------------------------------------------|
| Hours                    |                |      | 18, 19,<br>20, 21,<br>22                                                            |
| Seat                     |                |      | 23, 24                                                                              |
| A/C Controle             |                |      | 25, 26                                                                              |
| Cabin window             |                |      | 27, 28,<br>29, 30,<br>31, 32,<br>33                                                 |
| Roof                     |                |      | 34, 35                                                                              |
| Gearbox                  |                |      | 36, 37,<br>38                                                                       |
| gearbox-option           | Reversor       |      | 39                                                                                  |
| Steering-Wheel           |                |      | 40                                                                                  |
| Pedals                   |                |      | 41                                                                                  |
| Hydraulic Controls photo |                |      | 42, 43,<br>44                                                                       |
| command-type             | Simple Command |      |                                                                                     |
| Monitor                  |                |      | 45                                                                                  |
| Auto Guidance ready      | Yes            |      |                                                                                     |
| Transmission             | Semi-automatic |      | 46, 47                                                                              |



30

31

32



45

46


47

## Tyres

|                            | Value     | Note                                           |  |
|----------------------------|-----------|------------------------------------------------|-------------------------------------------------------------------------------------|
| Right Back Tyre            |           |                                                | 48                                                                                  |
| Right Back Tyre Condition  | Regular   |                                                |                                                                                     |
| Tyre image                 |           |                                                | 49                                                                                  |
| Left Back Tyre Condition   | Regular   |                                                |                                                                                     |
| Left Front Tyre            |           |                                                | 50                                                                                  |
| Left Front Tyre Condition  | Regular   |                                                |                                                                                     |
| Right Front Tyre           |           |                                                | 51                                                                                  |
| Right Front Tyre Condition | Regular   |                                                |                                                                                     |
| Tyre Condition             | Regular   |                                                |                                                                                     |
| Double Wheel               |           |                                                | 52, 53                                                                              |
| Tyre brand                 | Firestone | (4)TRASEIROS FIRESTONE<br>(2)DIANTERIOS FARMAX |                                                                                     |
| Tyre Tread                 |           |                                                | 54                                                                                  |
| Tyre Tread Left Back       |           |                                                | 55                                                                                  |
| Tyre Tread Right Front     |           |                                                | 56, 57                                                                              |
| Tyre Tread Right Back      |           |                                                | 58                                                                                  |




48



49



50



52



55



56



57



58

## Extra options



Value

Note



Breakdowns (more than 1 if necessary)


EQUIPAMENTO LIGA MAIS NAO DA  
PARTIDA RISCOS NA PINTURA 59, 60,  
PEQUENAS AVARIAS NO PAINEL 61, 62,  
CAIXA DE FUSÍVEL AVERTA SINAIS 63, 64,  
DE VIOLAÇÃO CONTEM 2 PNEUS 65, 66,  
FILIPADOS MARCA FIRESTONE 67, 68,  
PARALAMA TRASEIRO DIREITO COM 69, 70,  
AVARIAS PONTOS DE FERRUGENS 71, 72,  
NAS RODAS PARAFUSOS E 73, 74,  
ESCAPAMENTO PESOS DIANTEIRO 75  
ARRANADOS




65

66


67



69




72



73



74



75

Remarks

|               | Value                                                                                                                                                                                                                                                                                                                                   | Note |  |
|---------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------|-------------------------------------------------------------------------------------|
| Outside       |     |      |                                                                                     |
| Engine status |     |      |                                                                                     |
| Interior      |     |      |                                                                                     |

## Disclaimer

Please note that our inspections are performed solely for the purpose of reporting the visible condition of the equipment's major systems and attachments on the day of the inspection and do not include load testing or digging/lifting. These inspections are not designed nor intended to detect latent defects, or conditions that could only be found in connection with the physical dismantling of the equipment or the use of diagnostic tools or techniques. This inspection report includes ratings, comments, and photos of the various components of the item. Knowledgeable buyers are expected to carefully review all of the available information in the inspection report, including all photographs, in order to make the best bidding and buying decision possible.

The information provided in this inspection report is to the best knowledge of the Inspector accurate at the time at which the inspection was performed. Prospective buyers are recommended to undertake their own professional inspection of the equipment prior to completing any purchase of the equipment. All equipment is sold on an as is, where is basis with no commitment made by the seller as to suitability of use or fitness for purpose of the equipment.