




## Massey Ferguson MF 6714 2022

|                           |                      |
|---------------------------|----------------------|
| Make                      | Massey Ferguson      |
| Model                     | MF 6714              |
| Construction year         | 2022                 |
| Serial Number             | 6714666443           |
| Inspection date           | 28 Jan 2026          |
| Address of the inspection | Aparecida de Goiânia |









General

|            | Value | Note |  |
|------------|-------|------|-------------------------------------------------------------------------------------|
| Serial No  |       |      | 1, 2                                                                                |
| Chassis no |       |      | 3                                                                                   |



1




2





3

Open Hood









|                     | Value | Note |  |
|---------------------|-------|------|-------------------------------------------------------------------------------------|
| Engine              |       |      | 4, 5, 6                                                                             |
| Pump & Nozzle       |       |      | 7, 8, 9,<br>10                                                                      |
| Electrical          |       |      | 11, 12,<br>13, 14,<br>15, 16                                                        |
| Radiator            |       |      | 17, 18,<br>19, 20,<br>21                                                            |
| Battery photo       |       |      | 22                                                                                  |
| Running Engine      |       |      |                                                                                     |
| Hydraulic oil leaks | No    |      | 23, 24                                                                              |



7



9




22







23

24

## Equipment interior

|                          | Value          | Note          |  |
|--------------------------|----------------|---------------|-------------------------------------------------------------------------------------|
| Hours                    |                |               | 25                                                                                  |
| Seat                     |                |               | 26                                                                                  |
| A/C Controle             |                |               | 27, 28                                                                              |
| Cabin window             |                |               | 29, 30,<br>31, 32,<br>33, 34,<br>35                                                 |
| Roof                     |                |               | 36                                                                                  |
| Gearbox                  |                |               | 37                                                                                  |
| gearbox-option           | Multiplier     |               | 38                                                                                  |
| Steering-Wheel           |                |               | 39                                                                                  |
| Pedals                   |                |               | 40, 41                                                                              |
| Hydraulic Controls photo |                |               | 42, 43,<br>44, 45,<br>46                                                            |
| command-type             | Double Command |               | 47                                                                                  |
| Monitor                  |                | FALTA MONITOR | 48, 49                                                                              |
| Auto Guidance ready      | No             |               |                                                                                     |
| Transmission             | Automatic      |               | 50, 51,<br>52, 53,<br>54, 55,<br>56                                                 |






52

53

54



55



56

## Tyres

|                            | Value   | Note                                 |  |
|----------------------------|---------|--------------------------------------|-------------------------------------------------------------------------------------|
| Right Back Tyre            |         |                                      | 57                                                                                  |
| Right Back Tyre Condition  | Bad     |                                      |                                                                                     |
| Tyre image                 |         |                                      | 58                                                                                  |
| Left Back Tyre Condition   | Bad     |                                      |                                                                                     |
| Left Front Tyre            |         |                                      | 59                                                                                  |
| Left Front Tyre Condition  | Regular |                                      |                                                                                     |
| Right Front Tyre           |         |                                      | 60                                                                                  |
| Right Front Tyre Condition | Regular |                                      |                                                                                     |
| Tyre Condition             | Bad     |                                      |                                                                                     |
| Double Wheel               |         | NÃO                                  | 61, 62                                                                              |
| Tyre brand                 | Other   | DIANTERIOS : OZKA. TRASEIROS :CULTOR |                                                                                     |
| Tyre Tread                 |         |                                      | 63                                                                                  |
| Tyre Tread Left Back       |         |                                      | 64                                                                                  |
| Tyre Tread Right Front     |         |                                      | 65                                                                                  |
| Tyre Tread Right Back      |         |                                      | 66                                                                                  |





57



58



59



66

61

64

65

Extra options

Value

Note



Breakdowns (more than 1 if necessary)

EQUIPAMENTO COM LEVES RISCOS NA PINTURA, PARALAMAS DIANTEIROS ARRANHADOS, BOTÃO DO PARALAMA TRASEIRO LADO DIREITO AVARIADO, PONTOS DE FERRUGENS NO PESO DIANTEIRO E ESCAPAMANETO, INDENIZAÇÃO DO CAPO AVARIADA, BASE DOS RETROVISORES COM PINTURA RUIM, PNEUS TRASEIROS COM RACHADURAS NAO POSSUE MONITORES NEM ANTENA GPS

67, 68, 69, 70, 71, 72, 73, 74, 75, 76, 77, 78, 79, 80, 81, 82, 83, 84



70



68




71



72



74



77



80



82



83



84

Remarks

|               | Value                                                                                                                                                                                                                                                                                                                                   | Note |  |
|---------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------|-------------------------------------------------------------------------------------|
| Outside       |     |      |                                                                                     |
| Engine status |     |      |                                                                                     |
| Interior      |     |      |                                                                                     |

## Disclaimer

Please note that our inspections are performed solely for the purpose of reporting the visible condition of the equipment's major systems and attachments on the day of the inspection and do not include load testing or digging/lifting. These inspections are not designed nor intended to detect latent defects, or conditions that could only be found in connection with the physical dismantling of the equipment or the use of diagnostic tools or techniques. This inspection report includes ratings, comments, and photos of the various components of the item. Knowledgeable buyers are expected to carefully review all of the available information in the inspection report, including all photographs, in order to make the best bidding and buying decision possible.

The information provided in this inspection report is to the best knowledge of the Inspector accurate at the time at which the inspection was performed. Prospective buyers are recommended to undertake their own professional inspection of the equipment prior to completing any purchase of the equipment. All equipment is sold on an as is, where is basis with no commitment made by the seller as to suitability of use or fitness for purpose of the equipment.